

BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
69 May	14211	30x123	7/24/2015

SITE CONDITIONS:	Dry, sunny.
AMOUNT OF TOPSOIL USED ON SITE:	40 yards
HYDRO SEED/HAND SEED:	Hand seed
AMOUNT OF SEED USED ON SITE:	18.45 pounds
MACHINERY USED:	Skidsteer with scarifier and bucket, rakes, seed spreader, roller.
RUBBLE/DEBRIS, TYPE:	Rubble upturned during scarification from demolition in-fill.
RAINCHECK SIGN:	
FURTHER NOTES:	Tires dumped in lot had to be removed.
PHOTOGRAPHS OF SITE:	Before (1,2) and After, attached below.

Before:



1.



2.

After:



BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
38 Townsend	14206	35x100	7/13/2015

SITE CONDITIONS:	Sunny, dry.
AMOUNT OF TOPSOIL USED ON SITE:	40 yards
HYDRO SEED/HAND SEED:	Hand seed
AMOUNT OF SEED USED ON SITE:	17.5 pounds
MACHINERY USED:	Skidsteer with scarifier and bucket, rakes, seed spreader, roller.
RUBBLE/DEBRIS, TYPE:	In-fill rocky
RAINCHECK SIGN:	
PHOTOGRAPHS OF SITE:	Before (1,2) and After, attached below.

Before:



After:



BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
71 May	14211	30x123	7/24/2015

SITE CONDITIONS:	Dry, sunny
AMOUNT OF TOPSOIL USED ON SITE:	40 yards
HYDRO SEED/HAND SEED:	Hand seed
AMOUNT OF SEED USED ON SITE:	18.45 pounds
MACHINERY USED:	Skidsteer with scarifier and bucket, rakes, seed spreader, roller.
RUBBLE/DEBRIS, TYPE:	Small rubble from demolition
RAINCHECK SIGN:	
FURTHER NOTES:	Tires that had been dumped had to be removed from the site prior to installation.
PHOTOGRAPHS OF SITE:	Before and After, attached below.

Before:



After:



BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
116 Playter	14212	30x90	7/30/2015

SITE CONDITIONS:	Dry, sunny, hot
AMOUNT OF TOPSOIL USED ON SITE:	40 yards
HYDRO SEED/HAND SEED:	Hand seed
AMOUNT OF SEED USED ON SITE:	14 pounds
MACHINERY USED:	Skidsteer with scarifier and bucket, rakes, seed spreader, roller.
RUBBLE/DEBRIS, TYPE:	Rocks and roots.
RAINCHECK SIGN:	
PHOTOGRAPHS OF SITE:	Before (1, 2) and After, attached below.

Before:



After:



BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
128 Strauss	14212	30x139	7/17/2015

SITE CONDITIONS:	Dry and cloudy
AMOUNT OF TOPSOIL USED ON SITE:	50 yards
HYDRO SEED/HAND SEED:	Hydro seed
AMOUNT OF SEED USED ON SITE:	21 pounds
MACHINERY USED:	Skidsteer with bucket and scarifier, rakes, seed spreader, roller.
RUBBLE/DEBRIS, TYPE:	Very large concrete slabs, large sticks
RAINCHECK SIGN:	
PHOTOGRAPHS OF SITE:	Before (1,2) and After, attached below.

Before:



After:



BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
341 Paderewski	14212	30x101	7/23/2015

SITE CONDITIONS:	Dry, very sloped site
AMOUNT OF TOPSOIL USED ON SITE:	50 yards
HYDRO SEED/HAND SEED:	Hand seed
AMOUNT OF SEED USED ON SITE:	15 pounds
MACHINERY USED:	Skidsteer with scarifier and bucket, rakes, seed spreader, roller.
RUBBLE/DEBRIS, TYPE:	Rocky in-fill
RAINCHECK SIGN:	
FURTHER NOTES:	Significant slope and low areas requiring additional soil.
PHOTOGRAPHS OF SITE:	Before (1,2) and After, attached below.

Before:



After:



BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
388 Paderewski	14212	30x76	7/31/2015

SITE CONDITIONS:	Sunny, dry
AMOUNT OF TOPSOIL USED ON SITE:	40 yards
HYDRO SEED/HAND SEED:	Hand seed
AMOUNT OF SEED USED ON SITE:	11.5 pounds
MACHINERY USED:	Skidsteer with scarifier and bucket, rakes, seed spreader, roller.
RUBBLE/DEBRIS, TYPE:	In-fill rocky, large stones
RAINCHECK SIGN:	
PHOTOGRAPHS OF SITE:	Before (1, 2) and After, attached below.

Before:



After:

