

## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
37 Goembel	14212	30 X 150	9/11/15

<b>SITE CONDITIONS:</b>	Sunny, dry soil
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro Seed
<b>AMOUNT OF SEED USED ON SITE:</b>	21 pounds
<b>MACHINERY USED:</b>	Skidsteer, Harley Rake, Hydro Seeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Rock, Stone, Wood
<b>RAINCHECK SIGN:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
47 Gittere	14212	30 X 107	9/11/15

<b>SITE CONDITIONS:</b>	Sunny, Dry Soil Condition
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 Yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro Seeded
<b>AMOUNT OF SEED USED ON SITE:</b>	21 lbs.
<b>MACHINERY USED:</b>	Skidsteer, Harley Rake, Hydro Seeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Rock, Stone, Wood
<b>RAINCHECK SIGN:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



1.



2.

After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
81 Alma	14212	30 X 120	9/11/15

<b>SITE CONDITIONS:</b>	Sunny, dry soil
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydroseed
<b>AMOUNT OF SEED USED ON SITE:</b>	21 pounds
<b>MACHINERY USED:</b>	Skidsteer, Harley Rake, Hydro Seeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Rock, Stone, Wood
<b>RAINCHECK SIGN:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
109 Woods	14212	30 X 105	9/18/15

<b>SITE CONDITIONS:</b>	Sunny, Dry Soil Condition
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 Yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro Seeded
<b>AMOUNT OF SEED USED ON SITE:</b>	21 pounds
<b>MACHINERY USED:</b>	Skidsteer, Harley Rake, Hydro Seeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Rock, Stone, Wood
<b>FURTHER NOTES:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
129 Sprenger	14212	30 X 159	9/18/15

<b>SITE CONDITIONS:</b>	Sunny, Dry Soil Condition
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro Seed
<b>AMOUNT OF SEED USED ON SITE:</b>	21 pounds
<b>MACHINERY USED:</b>	Skidsteer, Harley Rake, Hydro Seeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Rock, Stone, Wood
<b>RAINCHECK SIGN:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before and Hydroseeding process, attached below.

Before:



1.



2.

Hydroseeding:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
399 Koons	14212	30 X 121	9/10/15

<b>SITE CONDITIONS:</b>	Sunny, dry soil
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro Seeded
<b>AMOUNT OF SEED USED ON SITE:</b>	21 pounds
<b>MACHINERY USED:</b>	Skidsteer, Harley Rake, Hydro Seeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Rock, Stone, Wood
<b>RAINCHECK SIGN:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
59 Carl	14215	30x140	9/1/2015

<b>SITE CONDITIONS:</b>	Dry, large chunks of concrete on site.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Small concrete from in-fill.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
77 Fernhill	14215	34x105	9/1/2105

<b>SITE CONDITIONS:</b>	Good
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Small rocks and concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



1.



2.

After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
115 Stevens	14215	30x100	9/1/2105

<b>SITE CONDITIONS:</b>	Fair, clay
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Small rocks
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
118 Stevens	14215	30x100	9/1/2105

<b>SITE CONDITIONS:</b>	Fair, clay
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Small rocks
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



1.



2.

After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
152 Clark	14212	30x90	9/1/2015

<b>SITE CONDITIONS:</b>	Good, dry, sandy.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Large concrete chunks, garbage and pipes dumped in site.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
214 Schuele	14215	30x140	9/1/2105

<b>SITE CONDITIONS:</b>	Rocky clay
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Large concrete pieces turned up during scarification.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
218 Stevens	14215	34x105	9/1/2105

<b>SITE CONDITIONS:</b>	Good
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Small rocks and concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
483 Dodge	14208	38.25x81	9/1/2015

<b>SITE CONDITIONS:</b>	Rough, dry, rocky
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Tree branches, concrete, garbage.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
744 Northland	14211	30x111	9/1/2105

<b>SITE CONDITIONS:</b>	Poor quality in-fill, lots of concrete chunks.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Pipes, tires, rocky, garbage
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
811 East Delevan	14215	unlisted	9/1/2015

<b>SITE CONDITIONS:</b>	Rough in-fill, garbage, concrete, site was graded closer to 6 inches and therefore deep.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	60 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	30 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Tree branches, concrete, garbage
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
845 East Ferry	14211	31x103	9/1/2015

<b>SITE CONDITIONS:</b>	Rough, rocky clay soil.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Fill was fair.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
16 C Street	14211	33x142	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, sandy, roots and brush.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Brush and roots
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
16 Swinburne	14212	30x115	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, rocky, branches dumped on site.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	22 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Small concrete turned up during scarification.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
28 Bissell	14211	30x105	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, debris, fair in-fill
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	81 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Fair fill
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



1.



2.

After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
45 Weber	14215	30x133	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, lots of plant roots, debris
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skidsteer, bucket, rock hound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Woody vegetation roots and concrete.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1.2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
72 Inter Park	14211	30x120	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, fair in-fill.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	24 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	No debris or rubble
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
82 Eller	14211	45x110	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, good, sandy.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skidsteer, bucket, rock hound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	None
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
162 Deerfield	14215	31x125	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, roots, and stones
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	50 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	24 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Lots of large stones, dumped.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and Hydroseeding process, attached below.

Before:



Hydroseeding:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
163 Brinkman	14211	30x115	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, roots and brush.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	22 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Large concrete debris
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
252 Wood	14211	30x100	9/4/2015

<b>SITE CONDITIONS:</b>	Dry, fair, sandy
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid steer, bucket, rock hound, scarifier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Fair, small concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
168 Metcalfe	14206	30x115	9/10/2015

<b>SITE CONDITIONS:</b> (Weather/Soil Conditions/Recent precipitation/etc.)	Sunny, dry
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	22 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Light debris, some concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
310 Paderewski	14212	28x80	9/10/2015

<b>SITE CONDITIONS:</b>	Sunny, dry, very low site
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	50 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	18 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Some rock and concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
785 South Division	14210	25x146	9/10/2015

<b>SITE CONDITIONS:</b>	Dry, sunny
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	50 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier, hydroseeder
<b>RUBBLE/DEBRIS, TYPE:</b>	Large concrete slabs and rocky fill.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
917 East Delevan	14215	20x30	9/10/2015

<b>SITE CONDITIONS:</b>	Sunny, dry
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rock hound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Paper debris, branches, rocky
<b>RAINCHECK SIGN:</b>	None
<b>FURTHER NOTES:</b>	None
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After: attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
130 Bissell	14211	30x105	9/18/2015

<b>SITE CONDITIONS:</b> (Weather/Soil Conditions/Recent precipitation/etc.)	Sunny, dry, sandy soil
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Fair
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
136 Box	14211	31x117	9/18/2015

<b>SITE CONDITIONS:</b> (Weather/Soil Conditions/Recent precipitation/etc.)	Sunny, dry, rough site, sloped grade
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	22 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Large concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
171 Brinkman	14211	30x115	9/18/2015

<b>SITE CONDITIONS:</b> (Weather/Soil Conditions/Recent precipitation/etc.)	New sidewalk has cracks, sunny, dry, sandy
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Small concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
191 Kilhoffer	14211	30x108	9/18/2015

<b>SITE CONDITIONS:</b>	Rough clay, sunny, dry
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Tree limbs, small concrete slabs.
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
195 Maple	14204	30x100	9/18/2015

<b>SITE CONDITIONS:</b>	Sunny, wet soil, shady, tree roots.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Rocky small concrete
<b>RAINCHECK SIGN:</b>	None
<b>FURTHER NOTES:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
208 Grape	14204	25x100	9/18/2015

<b>SITE CONDITIONS:</b>	Sunny, dry, fair.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	34 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Rocky sandy and tree roots
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2)and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
217 Grider	14215	30x140	9/18/2015

<b>SITE CONDITIONS:</b>	Sunny, dry, rough clay
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	50 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	25 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Many large stones
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:





## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
316 Goodyear	14211	30x110	9/18/2015

<b>SITE CONDITIONS:</b>	Sunny, dry.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	45 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Fair
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	N/A
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:



## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
396 Gibson	14212	30x110	9/18/2015

<b>SITE CONDITIONS:</b>	New sidewalk, sunny, dry, rough clay, exposed gas line.
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	40 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	20 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Large concrete
<b>RAINCHECK SIGN:</b>	
<b>FURTHER NOTES:</b>	NA
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After:

## BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
585 Fillmore	14212	30x125	9/18/2015

<b>SITE CONDITIONS:</b>	Sunny and dry, grade low
<b>AMOUNT OF TOPSOIL USED ON SITE:</b>	50 yards
<b>HYDRO SEED/HAND SEED:</b>	Hydro-seed
<b>AMOUNT OF SEED USED ON SITE:</b>	22 pounds
<b>MACHINERY USED:</b>	Skid-steer, bucket, rockhound, scarafier
<b>RUBBLE/DEBRIS, TYPE:</b>	Rocky sandy
<b>RAINCHECK SIGN:</b>	None
<b>FURTHER NOTES:</b>	
<b>PHOTOGRAPHS OF SITE:</b>	Before (1,2) and After, attached below.

Before:



After: