

BSA Completed Site Report

ADDRESS	ZIP CODE	FRONTAGE x DEPTH (ft)	DATE COMPLETED
1491 Broadway	14212	33.4x110	3/4/2015

SITE CONDITIONS: (Weather/Soil Conditions/Recent precipitation/etc.)	Dry, large concrete, low grade closer to 6 inches.
AMOUNT OF TOPSOIL USED ON SITE:	50 yards
HYDRO SEED/HAND SEED:	Hydro seed
AMOUNT OF SEED USED ON SITE:	22 pounds
MACHINERY USED:	Skid steer, bucket, rock hound, scarifier
RUBBLE/DEBRIS, TYPE:	Tires in lot, garbage, concrete chunks
RAINCHECK SIGN:	
FURTHER NOTES:	NA
PHOTOGRAPHS OF SITE:	Before and After, attached below.

Before:



After:

